



Erik Hopkins <erik.hopkins@empowerdigital.com>

Richmond d room 111.

1 message

Allen Carpenter-Rickert <acarpent@pps.net>

Tue, Apr 18, 2023 at 3:23 PM

To: Erik Hopkins <erik@empowerdigital.com>

Could you please take a look at this tomorrow? I really would appreciate it. I will be unable to do any change orderers, so make sure its right on.

Room 111.

(1) Data jack, which is coming apart at the faceplate, needs to be re-terminated.

(2) Data jack, with the cut cable needs to have a replacement Ethernet cable run installed. If the conduit is full, then another means of getting the cable to this area will be needed.

--

R Allen Carpenter-Rickert

Project Manager II

Portland Public Schools/Facilities and Asset Management

[501 North Dixon St. Portland, OR](#)

Direct-503.916.3977 I-Phone-503.888.9716

PDR Request Forms: https://www.pps.net/cms/lib/OR01913224/Centricity/Domain/58/PDR_2021.pdf

Facilities and Asset Management Home Page: <https://www.pps.net/Page/109>

Contractor Fingerprinting and Background Check Requirements: <https://www.pps.net/Page/184>

