



## Shaver Transportation – Camera Down

January 13, 2025

### Surveillance Solution

#### Scope of Work:

1. Troubleshoot down camera
2. Replace defective Gigabit extender
3. Confirm camera is up and running on the server

#### Items

Quantity	Description	Total Cost
3	Technical Labor	\$525.00
3	Installation Labor	450.00
1	Mobilization Fee	150.00
1	Gigabit PoE Extender	250.00
<b>TOTAL</b>		<b>\$1,375.00</b>

---

Signature

Date

---

Printed Name