



Erik Hopkins <erik.hopkins@empowerdigital.com>

Marshall Campus

1 message

Allen Carpenter-Rickert <acarpent@pps.net>
To: Erik Hopkins <erik@empowerdigital.com>

Mon, Mar 20, 2023 at 2:01 PM

Need to re-terminate data jack. Ethernet cable run goes from hallway to HDF 2-3, in room C-54 (Robes & Uniforms). **WAP - w43 - Hallway By Choir Rm B-62**



--
R Allen Carpenter-Rickert

Project Manager II
Portland Public Schools/Facilities and Asset Management
[501 North Dixon St. Portland, OR](https://www.pps.net)

Direct-503.916.3977 I-Phone-503.888.9716
PDR Request Forms: https://www.pps.net/cms/lib/OR01913224/Centricity/Domain/58/PDR_2021.pdf
Facilities and Asset Management Home Page: <https://www.pps.net/Page/109>
Contractor Fingerprinting and Background Check Requirements: <https://www.pps.net/Page/184>

