

Job Completion Checklist

The Job Description Wells Data Jack Repair Room 141 project for Customer Name Portland Public Schools has been completed. The checklist details are below.

Name: Erik Hopkins

Email: erik.hopkins@empowerdigital.com

Job Number: 2705E

Job Billing: Fixed Price

Customer Name: Portland Public Schools

Job Description: Wells Data Jack Repair Room 141

Project Status: Job Complete

All Cameras Installed: N/A

Ceiling Tile Replaced: N/A

Floor Vacuumed or Swept: Yes

Scrap Wire Cleaned Up: N/A

Monitors Installed: N/A

Cables Labeled: N/A

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A

Called for Final Inspection: N/A

All Trash Removed: Yes

Informed Customer of Completion: Yes

Printed Name: Erik Hopkins

Customer Sign Off:

A handwritten signature in black ink, appearing to read 'Erik Hopkins', written over a horizontal line.