

Job Completion Checklist

The Job Description Teevin Knappa Camera Outage - 20240201 project for Customer Name Teevin Brothers has been completed. The checklist details are below.

Name: Eric Halleen

Email: eric@arcconsultingsolutions.com

Job Number: 2884H

Job Billing: Fixed Price

Total Revenue: 2700

Customer Name: Teevin Brothers

Job Description: Teevin Knappa Camera Outage - 20240201

Project Status: Job Complete

Shipping Cost:

Change Order Amount:

Change Order Description:

All Cameras Installed: Yes

Ceiling Tile Replaced: N/A

Floor Vacuumed or Swept: N/A

Scrap Wire Cleaned Up: Yes

Monitors Installed: N/A

Cables Labeled: N/A

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A


Called for Final Inspection: N/A

All Trash Removed: Yes

Informed Customer of Completion: Yes

Printed Name: Eric Halleen

Customer Sign Off:



A handwritten signature in black ink, appearing to read 'Eric Halleen', is written over a horizontal line. The signature is stylized and cursive.