

Job Completion Checklist

The Job Description Teevin Camera Replacement / Server Move project for Customer Name Teevin Brothers has been completed. The checklist details are below.

Name: Eric Halleen

Email: eric@arcconsultingsolutions.com

Job Number: 2834H

Job Billing: Fixed Price

Total Revenue: 4233

Customer Name: Teevin Brothers

Job Description: Teevin Camera Replacement / Server Move

Project Status: Job Complete

Change Order Amount: 250

All Cameras Installed: Yes

Ceiling Tile Replaced: Yes

Floor Vacuumed or Swept: Yes

Scrap Wire Cleaned Up: Yes

Monitors Installed: Yes

Cables Labeled: Yes

Certification Report Saved: Yes

Lift Company Called for Pick Up: Yes

Called for Final Inspection: Yes

All Trash Removed: Yes

Informed Customer of Completion: Yes

Printed Name: Eric

Customer Sign Off:

A handwritten signature in black ink, appearing to read 'Eric Halleen', written over a horizontal line.