

Job Completion Checklist

The Job Description Access Control Repair - 20250613 project for Customer NameSeko Logistics has been completed. The checklist details are below.

Name: Eric Halleen

Email: eric@arcconsultingsolutions.com

Job Number: 3003H

Job Billing: Fixed Price

Total Revenue: 1900

Customer Name: Seko Logistics

Job Description: Access Control Repair - 20250613

Invoice Description:

Project Status: Job Complete

Shipping Cost:

Change Order Amount:

Change Order Description:

Additional Change Order Amount:

Additional Change Order Description:

All Cameras Installed: N/A

Ceiling Tile Replaced: N/A

Floor Vacuumed or Swept: N/A

Scrap Wire Cleaned Up: Yes

Monitors Installed: N/A

Cables Labeled: N/A

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A

Called for Final Inspection: N/A

All Trash Removed: Yes

Informed Customer of Completion: Yes

Printed Name: Eric Halleen

Customer Sign Off: