

Job Completion Checklist

The Job Description Test Project project for Customer Name ARC Consulting Solutions has been completed. The checklist details are below.

Name: Eric Halleen
Email: eric@arcconsultingsolutions.com
Job Number: 9999H
Job Billing: Time and Materials
Customer Name: ARC Consulting Solutions
Job Description: Test Project
Project Status: Job Complete
All Cameras Installed: Yes
Ceiling Tile Replaced: Yes
Floor Vacuumed or Swept: Yes
Scrap Wire Cleaned Up: Yes
Monitors Installed: Yes
Cables Labeled: Yes
Certification Report Saved: Yes
Lift Company Called for Pick Up: Yes
Called for Final Inspection: Yes
All Trash Removed: Yes
Informed Customer of Completion: Yes
Printed Name:
Customer Sign Off:
Start Date: 11/15/2022
Completion Date: 11/15/2022
Cat. 6 CMR Cable:
Cat. 6 (Direct Burial):
Cat. 6 Inserts: 2
1-Port Faceplate:
2-Port Faceplate:
24-Port Unpopulated Patch Panel:
48-Port Unpopulated Patch Panel:
Patch Panel Insert Jacks: 2
1' Cat. 6 Patch Cords:
3' Cat. 6 Patch Cords:
7' Cat. 6 Patch Cords:
10' Cat. 6 Patch Cords:
25' Cat. 6 Patch Cords:
1-Port Biscuit Jack:
1/2" EMT Conduit:
3/4" EMT Conduit: 6
1" EMT Conduit:
1-1/2" EMT Conduit:
2" EMT Conduit:
Limited Energy Permit:
Limited Energy Permit (Minor Label):
Item: Stuff
Quantity: 2

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Regular Hours: 3

Overtime Hours:

Travel Time (if separate from hours):

Regular Hours: 1

Overtime Hours:

Travel Time (if separate from hours):

Regular Hours: 2

Overtime Hours:

Travel Time (if separate from hours):

: