

Job Completion Checklist

The Job Description Grant High School Microphone Cable Repair project for Customer Name Portland Public Schools has been completed. The checklist details are below.

Name: Eric Halleen

Email: eric@arcconsultingsolutions.com

Job Number: 2586E

Job Billing: Time and Materials

Value: 3

Customer Name: Portland Public Schools

Job Description: Grant High School Microphone Cable Repair

Project Status: Job Complete

All Cameras Installed: N/A

Ceiling Tile Replaced: N/A

Floor Vacuumed or Swept: N/A

Scrap Wire Cleaned Up: N/A

Monitors Installed: N/A

Cables Labeled: N/A

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A

Called for Final Inspection: N/A

All Trash Removed: N/A

Informed Customer of Completion: N/A

Notes: !!!TEST!!!

Job Number: 2586E

Customer Name: Portland Public Schools

Job Description: Grant High School Microphone Cable Repair

Customer Sign-off Required?: No

Printed Name:

Customer Sign Off:

Job Number: 2586E

Customer Name: Portland Public Schools

Job Description: Grant High School Microphone Cable Repair

Start Date: 12/17/2021

Completion Date: 12/17/2021

Cat. 6 CMR Cable: 12

Cat. 6 (Direct Burial): 23

Cat. 6 Inserts:

1-Port Faceplate:

2-Port Faceplate:

24-Port Unpopulated Patch Panel:

48-Port Unpopulated Patch Panel:

Patch Panel Insert Jacks:

1' Cat. 6 Patch Cords: 23

3' Cat. 6 Patch Cords:

7' Cat. 6 Patch Cords:

10' Cat. 6 Patch Cords:

25' Cat. 6 Patch Cords:

1-Port Biscuit Jack:

1/2" EMT Conduit:

3/4" EMT Conduit: 123

1" EMT Conduit:

1-1/2" EMT Conduit:

2" EMT Conduit:

Limited Energy Permit:

Limited Energy Permit (Minor Label):

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Regular Hours:

Overtime Hours:

Travel Time (if separate from hours):

Regular Hours:

Overtime Hours:

Travel Time (if separate from hours):

Regular Hours:

Overtime Hours:

Travel Time (if separate from hours):

: