

Job Completion Checklist

The Job Description Camera Outage project for Customer Name Holiday Inn Express - Pullman has been completed. The checklist details are below.

Name: Eric Halleen
Email: eric@arcconsultingsolutions.com
Job Number: 2676H
Job Billing: Time and Materials
Customer Name: Holiday Inn Express - Pullman
Job Description: Camera Outage
Project Status: Job Complete
All Cameras Installed: N/A
Ceiling Tile Replaced: N/A
Floor Vacuumed or Swept: N/A
Scrap Wire Cleaned Up: N/A
Monitors Installed: N/A
Cables Labeled: N/A
Certification Report Saved: N/A
Lift Company Called for Pick Up: N/A
Called for Final Inspection: N/A
All Trash Removed: N/A
Informed Customer of Completion: Yes
Printed Name: Eric Halleen
Customer Sign Off:



Start Date: 07/30/2022
Completion Date: 07/30/2022
Cat. 6 CMR Cable:
Cat. 6 (Direct Burial):
Cat. 6 Inserts:
1-Port Faceplate:
2-Port Faceplate:
24-Port Unpopulated Patch Panel:
48-Port Unpopulated Patch Panel:
Patch Panel Insert Jacks:
1' Cat. 6 Patch Cords:
3' Cat. 6 Patch Cords:
7' Cat. 6 Patch Cords:
10' Cat. 6 Patch Cords:
25' Cat. 6 Patch Cords:

1-Port Biscuit Jack:

1/2" EMT Conduit:

3/4" EMT Conduit:

1" EMT Conduit:

1-1/2" EMT Conduit:

2" EMT Conduit:

Limited Energy Permit:

Limited Energy Permit (Minor Label):

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Regular Hours:

Overtime Hours:

Travel Time (if separate from hours):

Regular Hours:

Overtime Hours:

Travel Time (if separate from hours):

Regular Hours: 4

Overtime Hours:

Travel Time (if separate from hours):

: