

Job Completion Checklist

The Job Description Camera Troubleshooting project for Customer Name Vitro Glass Coating has been completed. The checklist details are below.

Name: Eric Halleen

Email: eric@arcconsultingsolutions.com

Job Number: 2617H

Job Billing: Fixed Price

Customer Name: Vitro Glass Coating

Job Description: Camera Troubleshooting

Project Status: Job Complete

All Cameras Installed: N/A

Ceiling Tile Replaced: N/A

Floor Vacuumed or Swept: N/A

Scrap Wire Cleaned Up: N/A

Monitors Installed: N/A

Cables Labeled: N/A

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A

Called for Final Inspection: N/A

All Trash Removed: N/A

Informed Customer of Completion: Yes

Printed Name: Eric Halleen

Customer Sign Off:

A handwritten signature in black ink, appearing to read "Eric Halleen", written over a horizontal line.