

Job Completion Checklist

The Job Description Camera Replacement - 9/14 project for Customer Name Albina Pipe has been completed. The checklist details are below.

Name: Eric Halleen

Email: eric@arcconsultingsolutions.com

Job Number: 2833H

Job Billing: Fixed Price

Total Revenue: 1035

Customer Name: Albina Pipe

Job Description: Camera Replacement - 9/14

Project Status: Job Complete

Change Order Amount: 350

All Cameras Installed: Yes

Ceiling Tile Replaced: Yes

Floor Vacuumed or Swept: Yes

Scrap Wire Cleaned Up: Yes

Monitors Installed: N/A

Cables Labeled: Yes

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A

Called for Final Inspection: N/A

All Trash Removed: Yes

Informed Customer of Completion: Yes

Printed Name: Eric Halleen

Customer Sign Off:


