

## Job Completion Checklist

The Job Description Switch Replacement project for Customer Name Courtyard Richland has been completed. The checklist details are below.

Name: Eric Halleen

Email: eric@arcconsultingsolutions.com

Job Number: 2606H

Job Billing: Time and Materials

Customer Name: Courtyard Richland

Job Description: Switch Replacement

Project Status: Job Complete

All Cameras Installed: Yes

Ceiling Tile Replaced: Yes

Floor Vacuumed or Swept: Yes

Scrap Wire Cleaned Up: N/A

Monitors Installed: N/A

Cables Labeled: N/A

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A

Called for Final Inspection: N/A

All Trash Removed: Yes

Informed Customer of Completion: Yes

Printed Name: Eric Halleen

Customer Sign Off:



---

Start Date: 04/04/2022

Completion Date: 06/04/2022

Cat. 6 CMR Cable:

Cat. 6 (Direct Burial):

Cat. 6 Inserts:

1-Port Faceplate:

2-Port Faceplate:

24-Port Unpopulated Patch Panel:

48-Port Unpopulated Patch Panel:

Patch Panel Insert Jacks:

1' Cat. 6 Patch Cords:

3' Cat. 6 Patch Cords:

7' Cat. 6 Patch Cords:

10' Cat. 6 Patch Cords:

25' Cat. 6 Patch Cords:

1-Port Biscuit Jack:

1/2" EMT Conduit:

3/4" EMT Conduit:

1" EMT Conduit:

1-1/2" EMT Conduit:

2" EMT Conduit:

Limited Energy Permit:

Limited Energy Permit (Minor Label):

Item: Switch (\$304.50)

Quantity: 1

Item: Shipping (\$50)

Quantity: 1

Item: Kitchen Camera (\$363)

Quantity: 1

Item: Porte-Co Camera (\$336)

Quantity: 1

Item: Lodging (\$67)

Quantity: 1

Regular Hours:

Overtime Hours:

Travel Time (if separate from hours):

Regular Hours:

Overtime Hours:

Travel Time (if separate from hours):

Regular Hours: 8

Overtime Hours:

Travel Time (if separate from hours): 9

: