


## Job Completion Checklist

The Job Description Server Maintenance project for Customer Name Polyform has been completed. The checklist details are below.

Name: Eric Halleen  
Email: eric@arcconsultingsolutions.com  
Job Number: 2603H  
Job Billing: Time and Materials  
Customer Name: Polyform  
Job Description: Server Maintenance  
Project Status: Job Complete  
All Cameras Installed: N/A  
Ceiling Tile Replaced: N/A  
Floor Vacuumed or Swept: N/A  
Scrap Wire Cleaned Up: N/A  
Monitors Installed: N/A  
Cables Labeled: N/A  
Certification Report Saved: N/A  
Lift Company Called for Pick Up: N/A  
Called for Final Inspection: N/A  
All Trash Removed: N/A  
Informed Customer of Completion: Yes  
Printed Name: Eric Halleen  
Customer Sign Off:

A handwritten signature in black ink, appearing to read 'Eric Halleen', is written over a solid horizontal line. The signature is stylized and cursive.

Start Date: 02/14/2022  
Completion Date: 02/14/2022  
Cat. 6 CMR Cable:  
Cat. 6 (Direct Burial):  
Cat. 6 Inserts:  
1-Port Faceplate:  
2-Port Faceplate:  
24-Port Unpopulated Patch Panel:  
48-Port Unpopulated Patch Panel:  
Patch Panel Insert Jacks:  
1' Cat. 6 Patch Cords:  
3' Cat. 6 Patch Cords:  
7' Cat. 6 Patch Cords:  
10' Cat. 6 Patch Cords:  
25' Cat. 6 Patch Cords:

1-Port Biscuit Jack:

1/2" EMT Conduit:

3/4" EMT Conduit:

1" EMT Conduit:

1-1/2" EMT Conduit:

2" EMT Conduit:

Limited Energy Permit:

Limited Energy Permit (Minor Label):

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Regular Hours:

Overtime Hours:

Travel Time (if separate from hours):

Regular Hours:

Overtime Hours:

Travel Time (if separate from hours):

Regular Hours: 2

Overtime Hours:

Travel Time (if separate from hours):

: