

Job Completion Checklist

The Job Description Camera System Service project for Customer Name Oregon Wine Services & Storage has been completed. The checklist details are below.

Name: Eric Halleen

Hidden: 4

Email: eric@arcconsultingsolutions.com

Job Number: 2562E

Customer Name: Oregon Wine Services & Storage

Job Description: Camera System Service

All Cameras Installed: N/A

Ceiling Tile Replaced: N/A

Floor Vacuumed or Swept: N/A

Scrap Wire Cleaned Up: N/A

Monitors Installed: N/A

Cables Labeled: N/A

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A

Called for Final Inspection: N/A

All Trash Removed: N/A


Informed Customer of Completion: N/A

Notes: Configured laptop to view cameras in office.

Customer Sign-off Required?:

Printed Name: Eric Halleen

Customer Sign Off:

A handwritten signature in black ink, appearing to read 'Eric Halleen'. The signature is stylized with a large, sweeping initial 'E' and a long, horizontal tail that ends in a small loop.