

Job Completion Checklist

The Job Description Footage Assistance project for Customer Name Hiton Garden Inn Boren has been completed. The checklist details are below.

Name: Eric Halleen

Email: eric@arcconsultingsolutions.com

Job Number: 2731H

Job Billing: Time and Materials

Customer Name: Hiton Garden Inn Boren

Job Description: Footage Assistance

Project Status: Job Complete

All Cameras Installed: N/A

Ceiling Tile Replaced: N/A

Floor Vacuumed or Swept: N/A

Scrap Wire Cleaned Up: N/A

Monitors Installed: N/A

Cables Labeled: N/A

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A

Called for Final Inspection: N/A

All Trash Removed: N/A

Informed Customer of Completion: Yes

Printed Name:

Customer Sign Off:

Start Date: 12/04/2022

Completion Date: 12/04/2022

Cat. 6 CMR Cable:

Cat. 6 (Direct Burial):

Cat. 6 Inserts:

1-Port Faceplate:

2-Port Faceplate:

24-Port Unpopulated Patch Panel:

48-Port Unpopulated Patch Panel:

Patch Panel Insert Jacks:

1' Cat. 6 Patch Cords:

3' Cat. 6 Patch Cords:

7' Cat. 6 Patch Cords:

10' Cat. 6 Patch Cords:

25' Cat. 6 Patch Cords:

1-Port Biscuit Jack:

1/2" EMT Conduit:

3/4" EMT Conduit:

1" EMT Conduit:

1-1/2" EMT Conduit:

2" EMT Conduit:

Limited Energy Permit:

Limited Energy Permit (Minor Label):

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Item:

Quantity:

Regular Hours:

Overtime Hours:

Travel Time (if separate from hours):

Regular Hours:

Overtime Hours:

Travel Time (if separate from hours):

Regular Hours: 2

Overtime Hours:

Travel Time (if separate from hours):

: