

## Job Completion Checklist

The Job Description Verkada Camera Additions project for Customer Name Holiday Inn Express - Pullman has been completed. The checklist details are below.

Name: Eric Halleen

Email: eric@arcconsultingsolutions.com

Job Number: 2779H

Job Billing: Fixed Price

Total Revenue: 19779

Customer Name: Holiday Inn Express - Pullman

Job Description: Verkada Camera Additions

Project Status: Job Complete

Shipping Cost:

Change Order Amount:

Change Order Description:

Additional Change Order Amount:

Additional Change Order Description:

All Cameras Installed: Yes

Ceiling Tile Replaced: Yes

Floor Vacuumed or Swept: Yes

Scrap Wire Cleaned Up: Yes

Monitors Installed: N/A

Cables Labeled: Yes

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A

Called for Final Inspection: N/A

All Trash Removed: Yes

Informed Customer of Completion: Yes

Printed Name:

Customer Sign Off: