

## Job Completion Checklist

The Job Description New 180 and Camera Swap project for Customer Name Denton Plastics has been completed. The checklist details are below.

Name: Eric Halleen

Email: eric@arcconsultingsolutions.com

Job Number: 2835H

Job Billing: Fixed Price

Total Revenue: 1600

Customer Name: Denton Plastics

Job Description: New 180 and Camera Swap

Project Status: Job Complete

Change Order Amount: 100

All Cameras Installed: Yes

Ceiling Tile Replaced: Yes

Floor Vacuumed or Swept: Yes

Scrap Wire Cleaned Up: Yes

Monitors Installed: N/A

Cables Labeled: N/A

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A


Called for Final Inspection: N/A

All Trash Removed: Yes

Informed Customer of Completion: Yes

Printed Name: Eric Halleen

Customer Sign Off:



---