

Job Completion Checklist

The Job Description McMinnville Maintenance Station Camera Upgrade project for Customer Name ODOT has been completed. The checklist details are below.

Name: Erik Hopkins

Email: erik.hopkins@empowerdigital.com

Job Number: 2797E

Job Billing: Fixed Price

Customer Name: ODOT

Job Description: McMinnville Maintenance Station Camera Upgrade

Project Status: Job Complete

All Cameras Installed: Yes

Ceiling Tile Replaced: N/A

Floor Vacuumed or Swept: Yes

Scrap Wire Cleaned Up: Yes

Monitors Installed: N/A

Cables Labeled: Yes

Certification Report Saved: Yes

Lift Company Called for Pick Up: N/A

Called for Final Inspection: N/A

All Trash Removed: Yes

Informed Customer of Completion: Yes

Printed Name: Erik Hopkins

Customer Sign Off:

A handwritten signature in black ink, appearing to be a stylized name, possibly "Erik Hopkins".
