

Job Completion Checklist

The Job Description Exterior Camera Replacement - 20250103 project for Customer Name Oregon Publishing & Distribution has been completed. The checklist details are below.

Name: Eric Halleen

Email: eric@arcconsultingsolutions.com

Job Number: 2957H

Job Billing: Fixed Price

Total Revenue: 1650

Customer Name: Oregon Publishing & Distribution

Job Description: Exterior Camera Replacement - 20250103

Project Status: Job Complete

Shipping Cost:

Change Order Amount:

Change Order Description:

Additional Change Order Amount:

Additional Change Order Description:

All Cameras Installed: Yes

Ceiling Tile Replaced: N/A

Floor Vacuumed or Swept: N/A

Scrap Wire Cleaned Up: N/A

Monitors Installed: N/A

Cables Labeled: N/A

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A

Called for Final Inspection: N/A

All Trash Removed: Yes

Informed Customer of Completion: Yes

Printed Name: Eric Halleen

Customer Sign Off:

A handwritten signature in black ink, appearing to read "Eric Halleen", is written over a horizontal line. The signature is stylized and somewhat cursive.