

Job Completion Checklist

The Job Description Camera Re-Mount project for Customer Name Kendal Floral has been completed. The checklist details are below.

Name: Eric Halleen

Email: eric@arcconsultingsolutions.com

Job Number: 2808H

Job Billing: Time and Materials

Total Revenue: 200

Customer Name: Kendal Floral

Job Description: Camera Re-Mount

Project Status: Job Complete

Change Order Amount:

Change Order Description:

All Cameras Installed: Yes

Ceiling Tile Replaced: Yes

Floor Vacuumed or Swept: Yes

Scrap Wire Cleaned Up: Yes

Monitors Installed: N/A

Cables Labeled: Yes

Certification Report Saved: N/A

Lift Company Called for Pick Up: N/A

Called for Final Inspection: N/A

All Trash Removed: Yes

Informed Customer of Completion: Yes

Printed Name: Eric Halleen

Customer Sign Off:



Start Date: 10/30/2023

Completion Date: 10/30/2023

Cat. 6 CMR Cable: 20

Cat. 6 (Direct Burial):

Cat. 6 Inserts:

1-Port Faceplate:

2-Port Faceplate:

24-Port Unpopulated Patch Panel:

48-Port Unpopulated Patch Panel:

Patch Panel Insert Jacks: 1

1' Cat. 6 Patch Cords:

3' Cat. 6 Patch Cords:

7' Cat. 6 Patch Cords:
10' Cat. 6 Patch Cords:
25' Cat. 6 Patch Cords:
1-Port Biscuit Jack:
1/2" EMT Conduit:
3/4" EMT Conduit: 2
1" EMT Conduit:
1-1/2" EMT Conduit:
2" EMT Conduit:
Limited Energy Permit:
Limited Energy Permit (Minor Label):
Item: Miscellaneous Materials (\$100)
Quantity: 1
Item:
Quantity:
Item:
Quantity:
Item:
Quantity:
Item:
Quantity:
Item:
Quantity:
Regular Hours: 8
Overtime Hours:
Travel Time (if separate from hours):
Regular Hours: 8
Overtime Hours:
Travel Time (if separate from hours):
Regular Hours: 6
Overtime Hours:
Travel Time (if separate from hours):
: